

THE CITY OF NEW YORK
DEPARTMENT OF HOUSING PRESERVATION AND DEVELOPMENT
DIVISION OF CODE ENFORCEMENT



DIVISION OF CODE ENFORCEMENT
105 East 106 Street, 4th Floor
New York, NY 10029

BLDG ID	BORO	HOUSE NO	STREET NAME	COMPLAINT #	CYCLE #	PRINT DATE	PAGE
383522	BK	208	UNION STREET	3822592	59800	05/22/2007	1 of 2

**SUMMARY NOTICE OF LEAD-BASED PAINT INSPECTION/ISSUANCE OF
VIOLATIONS FOR LEAD-BASED PAINT**

Occupant of Apt: 3
208 UNION STREET Apt #: 3
BROOKLYN NY - 11231

This Summary Notice of Inspection applies to the above referenced address and apartment.

Inspection Date: 05/17/2007

Summary of Inspection Results:

Viol #	Room Location/Offset	Component	Result
6756395	1st ROOM FROM NORTH AT EAST	1st DOOR FRAME FROM EAST AT SOUTH WALL	Positive
	1st ROOM FROM NORTH AT EAST	CEILING	Negative
6756395	1st ROOM FROM NORTH AT EAST	EAST WALL	Positive
6756395	1st ROOM FROM NORTH AT EAST	SOUTH WALL	Positive
	1st ROOM FROM NORTH AT WEST	1st DOOR FROM EAST AT SOUTH WALL	Negative
6756396	1st ROOM FROM NORTH AT WEST	1st DOOR FROM NORTH AT EAST WALL	Positive
6756396	1st ROOM FROM NORTH AT WEST	1st DOOR FRAME FROM EAST AT SOUTH WALL	Positive
6756396	1st ROOM FROM NORTH AT WEST	1st WINDOW FRAME FROM WEST AT NORTH WALL	Positive
6756396	1st ROOM FROM NORTH AT WEST	2nd DOOR FRAME FROM NORTH AT EAST WALL	Positive
6756396	1st ROOM FROM NORTH AT WEST	2nd WINDOW FRAME FROM WEST AT NORTH WALL	Positive
	1st ROOM FROM NORTH AT WEST	CEILING	Negative
	1st ROOM FROM NORTH AT WEST	SOUTH WALL	Negative
	1st ROOM FROM NORTH AT WEST	WEST WALL	Negative
6756398	2nd ROOM FROM NORTH	1st DOOR FROM NORTH AT EAST WALL	Positive
6756398	2nd ROOM FROM NORTH	1st DOOR FRAME FROM EAST AT SOUTH WALL	Positive
6756398	2nd ROOM FROM NORTH	1st DOOR FRAME FROM NORTH AT EAST WALL	Positive
6756398	2nd ROOM FROM NORTH	1st DOOR FRAME FROM WEST AT NORTH WALL	Positive
	2nd ROOM FROM NORTH	WEST WALL	Negative
6756397	BATHROOM	1st DOOR FROM SOUTH AT WEST WALL	Positive
	BATHROOM	1st DOOR FRAME FROM SOUTH AT WEST WALL	Negative
	BATHROOM	CEILING	Negative
	BATHROOM	EAST WALL	Negative
	BATHROOM	SOUTH WALL	Negative
	KITCHEN	1st WINDOW FRAME FROM EAST AT SOUTH WALL	Negative
	KITCHEN	EAST WALL	Negative
	KITCHEN	NORTH WALL	Negative

THE CITY OF NEW YORK
 DEPARTMENT OF HOUSING PRESERVATION AND DEVELOPMENT
 DIVISION OF CODE ENFORCEMENT



DIVISION OF CODE ENFORCEMENT
 105 East 106 Street, 4th Floor
 New York, NY 10029

BLDG ID	BORO	HOUSE NO	STREET NAME	COMPLAINT #	CYCLE #	PRINT DATE	PAGE
383522	BK	208	UNION STREET	3822592	59800	05/22/2007	2 of 2

SUMMARY NOTICE OF LEAD-BASED PAINT INSPECTION/ISSUANCE OF VIOLATIONS FOR LEAD-BASED PAINT

Occupant of Apt: 3
 208 UNION STREET Apt #: 3
 BROOKLYN NY - 11231

Inspection Date: 05/17/2007

Summary of Inspection Results:

Viol #	Room Location/Offset	Component	Result
	PRIVATE HALLWAY	NORTH WALL	Negative

Positive--A positive test result means that lead-based paint was found in the inspected areas and a lead-based paint hazard violation has been issued.

Negative--A negative test result means that lead-based paint was not found in the inspected areas

Inconclusive--An inconclusive test result on a metal surface means that the presence of lead-based paint was not definitely confirmed.

A lead-based paint hazard violation has been issued based upon the presumption of lead-based paint on the deteriorated surface identified on inspection. These violations may be contested by the owner, however, only paint chip sample testing may be used to contest the violations.

The owner of the building is responsible for correcting the violation. HPD must perform a re-inspection to verify the correction of the violation(s). It is important that the tenant provide access to the owner to correct the violation and to HPD to perform the re-inspection.

If you have any concerns regarding the work practices used to correct the violations or you believe that the work is creating lead hazards, you may contact the New York City Department of Health and Mental Hygiene at 311.