

THE CITY OF NEW YORK
DEPARTMENT OF HOUSING PRESERVATION AND DEVELOPMENT
DIVISION OF CODE ENFORCEMENT



DIVISION OF CODE ENFORCEMENT
105 East 106 Street, 4th Floor
New York, NY 10029

BLDG ID	BORO	HOUSE NO	STREET NAME	Apt #	CYCLE #	PRINT DATE	PAGE
383522	BK	208	UNION STREET	3	62439	07/19/2007	1 of 2

SUMMARY NOTICE OF LEAD-BASED PAINT VIOLATION RE-INSPECTION

Occupant of Apt: 3 208 UNION STREET Apt #: 3 BROOKLYN NY - 11231
--

Inspection Report:

The Department of Housing Preservation and Development (HPD) conducted an inspection for the correction of the following lead-based paint violations in the above referenced building/apartment with the result indicated below:

Violation #	Violation Description	Condition Status	Violation Status	Dust wipe clearance test result
6756398	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) 1st DOOR FROM NORTH AT EAST WALL, 1st DOOR FRAME FROM WEST AT NORTH WALL, 1st DOOR FRAME FROM EAST AT SOUTH WALL, 1st DOOR FRAME FROM NORTH AT EAST WALL IN THE 2nd ROOM FROM NORTH LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING
6756396	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) 1st DOOR FROM NORTH AT EAST WALL, 1st DOOR FRAME FROM EAST AT SOUTH WALL, 2nd DOOR FRAME FROM NORTH AT EAST WALL, 1st WINDOW FRAME FROM WEST AT NORTH WALL, 2nd WINDOW FRAME FROM WEST AT NORTH WALL IN THE 1st ROOM FROM NORTH AT WEST LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING
6756395	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) 1st DOOR FRAME FROM EAST AT SOUTH WALL, SOUTH WALL, EAST WALL IN THE 1st ROOM FROM NORTH AT EAST LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING
6745979	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) CEILING IN THE 1st ROOM FROM NORTH AT WEST LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING
6745978	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PRESUMED LEAD PAINT THAT IS PEELING OR ON A DETERIORATED SUBSURFACE USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) EAST WALL IN THE KITCHENETTE LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING

THE CITY OF NEW YORK
 DEPARTMENT OF HOUSING PRESERVATION AND DEVELOPMENT
 DIVISION OF CODE ENFORCEMENT



DIVISION OF CODE ENFORCEMENT
 105 East 106 Street, 4th Floor
 New York, NY 10029

BLDG ID	BORO	HOUSE NO	STREET NAME	Apt #	CYCLE #	PRINT DATE	PAGE
383522	BK	208	UNION STREET	3	62439	07/19/2007	2 of 2

SUMMARY NOTICE OF LEAD-BASED PAINT VIOLATION RE-INSPECTION

Occupant of Apt: 3
 208 UNION STREET Apt #: 3
 BROOKLYN NY - 11231

Violation #	Violation Description	Condition Status	Violation Status	Dust wipe clearance test result
6756397	§ 27-2056.6 ADM CODE - CORRECT THE LEAD-BASED PAINT HAZARD - PAINT THAT TESTED POSITIVE FOR LEAD CONTENT AND THAT IS PEELING OR ON A DETERIORATED SUBSURFACE - USING WORK PRACTICES SET FORTH IN 28 RCNY §11-06(B)(2) 1st DOOR FROM SOUTH AT WEST WALL IN THE BATHROOM LOCATED AT APT 3, 2nd STORY, 1st APARTMENT FROM SOUTH AT WEST	NO ACCESS TO INSPECT	OPEN	PENDING

If the result indicates that the condition has not been corrected, HPD will be attempting to obtain access to the apartment for the purpose of scheduling repairs.

CC: Owner