

THE CITY OF NEW YORK
DEPARTMENT OF HOUSING PRESERVATION AND DEVELOPMENT
DIVISION OF CODE ENFORCEMENT



DIVISION OF CODE ENFORCEMENT
105 East 106 Street, 4th Floor
New York, NY 10029

BLDG ID	BORO	HOUSE NO	STREET NAME	COMPLAINT #	CYCLE #	PRINT DATE	PAGE
383522	BK	208	UNION STREET	3809798	59542	05/15/2007	1 of 1

**SUMMARY NOTICE OF LEAD-BASED PAINT INSPECTION/ISSUANCE OF
VIOLATIONS FOR LEAD-BASED PAINT**

Occupant of Apt: 3
208 UNION STREET Apt #: 3
BROOKLYN NY - 11231

This Summary Notice of Inspection applies to the above referenced address and apartment.

Inspection Date: 05/10/2007

Summary of Inspection Results:

Viol #	Room Location/Offset	Component	Result
6745979	1st ROOM FROM NORTH AT WEST	CEILING	No Access
6745978	KITCHENETTE	EAST WALL	No Access

Positive--A positive test result means that lead-based paint was found in the inspected areas and a lead-based paint hazard violation has been issued.

Negative--A negative test result means that lead-based paint was not found in the inspected areas

Inconclusive--An inconclusive test result on a metal surface means that the presence of lead-based paint was not definitely confirmed.

A lead-based paint hazard violation has been issued based upon the presumption of lead-based paint on the deteriorated surface identified on inspection. These violations may be contested by the owner, however, only paint chip sample testing may be used to contest the violations.

The owner of the building is responsible for correcting the violation. HPD must perform a re-inspection to verify the correction of the violation(s). It is important that the tenant provide access to the owner to correct the violation and to HPD to perform the re-inspection.

If you have any concerns regarding the work practices used to correct the violations or you believe that the work is creating lead hazards, you may contact the New York City Department of Health and Mental Hygiene at 311.