

05/16/07
061027

HPD Building, Registration & Violation Services [Home](#)

The selected address: 208 UNION STREET, Brooklyn 11231												
HPD#	Range	Block	Lot	CD	CensusTract	Stories	A Units	B Units	Ownership	MDR#	Class	
383522	Active	208-208	00344	0016	6	6700	3	4	0	PVT	328832	G

- Other Units
- Property Registration Assistance
- Registration
- Emerg. Repairs
- Charges (PDF)
- Map
- Complaint Status
- Carbon Monoxide Certificate

Building Registration Summary Report

Owner	Last Reg Dt	Organization	Last Nm	First Nm	House No	Street Nm	Apt	City	State	Zip
Individual	2006/10/17		MATARAZZO	SANTO	208	UNION STREET	2	BROOKLYN	NY	11231

Open Violations - ALL DATES

There are 5 Violations. Arranged by category: A class: 0 B class: 2 C class: 3 I class: 0

For Definitions of the columns indicated below, select glossary under the Services option (located at the upper right).


To sort the columns, click on their underlined headers below in the blue area.

All Open Violations

prior year Open Viol.'s

Apt Story	Reported Date, nov ISSUED Date	Hzrd Class	Order no Item no	Violation ID, NOV ID	Violation Description	Status Status Date	Owner Certification Dates: 1st Lead, 2nd Lead
3 2	2007/05/10 2007/05/11	C	510 -	6741375 2970876	§ 27-2005 adm code & 309 m/d law abate the nuisance consisting of scalding hot water in the entire apartment located at apt 3, 2nd story, 1st apartment from south at west	NOV SENT 2007/05/11	2007/05/27 -
3 2	2007/05/10 2007/05/11	B	509 -	6741376 2970875	§ 27-2005 adm code properly secure the loose ceranic tile on the floor in the kitchen located at apt 3, 2nd story, 1st apartment from south at west	NOV SENT 2007/05/11	2007/07/04 -
3 2	2007/05/10 2007/05/11	B	502 -	6741377 2970875	§ 27-2005 adm code properly repair with similar material the broken or defective ceramic tile floor in the bathroom located at apt 3, 2nd story, 1st apartment from south at west	NOV SENT 2007/05/11	2007/07/04 -
3 2	2007/05/10 2007/05/15	C	616 -	6745978 2972980	§ 27-2056.6 adm code - correct the lead-based paint hazard - presumed lead paint that is peeling or on a deteriorated subsurface using work practices set forth in 28 rcny §11-06(b)(2) east wall in the kitchenette located at apt 3, 2nd story, 1st	NOV SENT 2007/05/15	2007/06/15 -

					apartment from south at west		
3	2007/05/10	C	616	6745979	§ 27-2056.6 adm code - correct the lead-based paint hazard - presumed lead paint that is peeling or on a deteriorated subsurface using work practices set forth in 28 rcny §11-06(b)(2) ceiling in the 1st room from north at west located at apt 3, 2nd story, 1st apartment from south at west	NOV SENT 2007/05/15	2007/06/15
2	2007/05/15	-	-	2972980			-

	Services News & Features City Life City Agencies Office of the Mayor Contact Us Search
	NYC.gov - NEW YORK CITY'S OFFICIAL WEB SITE